

ASSISTANCE SHEET

DATE

26/03/2018

Зип Общепит

vsezip.ru

+7(812)987-08-81

GENERAL INFORMATION

Assistance sheet code	SA84
Title description	Instruction replacement EXPLORA motor



SAFETY WARNING! The indications in this service file must be only performed by authorized technical service.
Any intervention done by non-authorized personal will invalidate the one-year factory warranty.
Piron is not liable for any damage caused to the equipment or any physical injuries occurring from actions performed not in accordance with the above indications.

PIRON[®]
your professional cooking

ASSISTANCE SHEET

DATE

26/03/2018

Зип Общепит


vsezip.ru

+7(812)987-08-81

To do 1:



Disconnect the oven from the power grid.



REMOVE
THE
MOTOR'S
COVER (IN
RED)
INSIDE THE
CAVITY



SAFETY WARNING! The indications in this service file must be only performed by authorized technical service. Any intervention done by non-authorized personal will invalidate the one-year factory warranty. Piron is not liable for any damage caused to the equipment or any physical injuries occurring from actions performed not in accordance with the above indications.

PIRON[®]
your professional cooking

ASSISTANCE SHEET

Зип Общепит

DATE

26/03/2018

vsezip.ru

+7(812)987-08-81

REMOVE
THE
IMPELLER
(IN RED)
INSIDE THE
CAVITY



SAFETY WARNING! The indications in this service file must be only performed by authorized technical service.
Any intervention done by non-authorized personal will invalidate the one-year factory warranty.
Piron is not liable for any damage caused to the equipment or any physical injuries occurring from actions performed not in accordance with the above indications.

PIRON[®]
your professional cooking

ASSISTANCE SHEET

Зип Общепит

DATE

26/03/2018

vsezip.ru

+7(812)987-08-81



REMOVE
THE BACK
OF THE
OVEN



SAFETY WARNING! The indications in this service file must be only performed by authorized technical service.
Any intervention done by non-authorized personal will invalidate the one-year factory warranty.
Piron is not liable for any damage caused to the equipment or any physical injuries occurring from actions performed not in accordance with the above indications.

PIRON[®]
your professional cooking

ASSISTANCE SHEET

DATE


26/03/2018

Випл. Общепит

vsezip.ru

+7(812)987-08-81

UNSCREW THE
SENSOR
MOTOR'S
,UNSCREWS
THE 4 SCREWS
AND PULL OUT
THE MOTOR .
CHANGE IT
AND FIX THE
SENSOR ON
THE NEW
MOTOR.FIX
THE MOTOR.



Reconnect the oven to the power grid