



Зип Общепит

ysezip.ru

+7(812)987-08-81



DETAIL A



MATERIAL	AREA m ²	DATE	ECN	3096					THIRD ANGLE PROJECTION ALL DIMENSIONS IN mm UNLESS OTHERWISE STATED	SHEET 1 OF 2	TITLE
ST		04.03.08	DATE	21.01.07							0E7503 - A001
DRAWN BY	SCALE	GENERAL TOLERANCE ± 0.4mm			GRAIN ALONG X AXIS U.O.S.			BURR SIDE DOWN U.O.S.			REVISION
Kevin Hanson	NTS(A3)	Lincat			© 2008 LINCAT LIMITED, WHISBY ROAD, LINCOLN, LN6 3QZ			DWG No.			

R&D Component Request Sheet

Date Requested	04/06/2008		
Name	Ian Marshall		
Product			
Description	OE7503 - A001		
Part Number	18801	Revision No	Error: No reference
Quantity			
Material	Bend Rad Error: No reference Mat Thick Error: No reference		
Processed by			
New DXF	Yes	ECN Number	3096
Folding/Perimeter			

Reason for request	Please Tick Box
Punching Fault	
Folding Error	
Scratched/Dented	
Shortage	
Development	Yes
Recon	
Spares	

DESTINATION